



ELECTROCENTRALE BUCUREȘTI S.A.

Splaiul Independenței nr. 227, cod poștal 060041, sector 6, București
Tel.: +4021.275.11.03, Fax: +4021.275.14.05
office@elcen.ro, www.elcen.ro
C.U.I.: 15189596, R.C.: J40/1696/2003



In atentie: posibili ofertanti

10672/03.04.2023

Referitor: Clarificari la documentatia de atribuire pentru achizitia directa cu nr:

ADV1354039 - Elemente de cauciuc (inele de cauciuc aferente EPA 500-180-1)- CTE PROGRESU – termen depunere 05.04.2023

Va transmitem raspunsul nostru la solicitarea de clarificari transmisa de un potential ofertant:

Intrebare:

„Va rugam sa ne transmiteti desenele garniturilor la care se face referire in Anexa 1? ”

Raspuns:

Regasiti atasat desenele solicitate.

DIRECTOR JURIDIC SI ACHIZITII

Mihai Darian VOLF

Sef Serviciu Achizitii

Roxana KEDEI

Sef BMAP

Anca ORDEAN


Responsabil achizitie

Irena ITU-CRISTEA

NOTA: A-4100-41

REV: 2

POZ: 18



17.77

6 buc/pompa

TURBINA

DESIGN

DEZINAT

ADNOTAT

Stratinsy S

Ing. L. Man M

Ing. Calman M

Ing. Blaru G

cauciuc PTH 70

STAS 1278-62

masa net 0.075 kg

Scara:

1-2

17.05.08/6

43

16-410-47

NR. MODIF: 0

ICSITEE
Bucuresti

Inel de cauciuc


ROTOR

Pompa

EPA 500-15

A4 (EPA) - 25.7.1

Ref:	A
Rev:	01
Doc:	13.2.3




Unghiul exterior 11
43-14-410-26

4 buc / pompa

Material	Cauciuc	PTH 70	776	43-14-410-26
Norma	STAS 7278-82			
Greutate	0.02 kg			
Stare	1-1			
Loc	ETANSARI			
Epoca	5.3.3			

ICSITEE h/pac Bucuresti

nr. nr.	A 4257-12
Rev	a
Poz.	2.22



ICSITEE Col. POMPE
Original deteriorat
43-14-410-28


M77

1 buc / pompa

Proiectat	Mehedinteanu	Cauciuc PTH70	43-14-410-28
Desenat	ing. Nabilovici	STAS 7278-82	
Verificat	ing. Nabilovici	Scara: 1:5	GARNITURĂ Ø 450/5
Contr. STAS	ing. Nabilovici	Data: 06.09.76	ETANSĂRI
Aprobat	ing. O. I. I.		EPA 500-180

ICSITEE
Bucuresti

Revizor	A 4194-01
Tip	11



φ520

φ8

(246)

Abuc / pomp

Desenat: Ing. E.
Verificat: Ing. Coman
Proiectat: Ing. Calin
Executat: Ing. Odruga

PTH 70
STAS 7278-82

43-10-409-61

Modificat: 0025/0 Nr. modif: 01

ILSITEE
Bucuresti

1:1

Garnitură 520x8

Data: 707/1976

Stator exterior

EFZ 500-1

A. 7067-15051


Originala detinuta
43-10-409-61/1

Proiectat: Ing. E.
Verificat: Ing. Coman
Proiectat: Ing. Calin
Executat: Ing. Odruga

Nr. ref: A4194-02

Rev: a

Poz: 12



$\phi 540$

$\phi 545$

ICSITFE - Col. Pompe

Orig. al deteriorat

43-10-409-62 / a

Proiectat
Desenat
Verificat
Contr. STAS
Aprobat

Stefan -
Ing. Calman
Ing. Calman
Ing. Olaru

PTH 70
STAS 7278-82

Masa netă: 0014 kg

nr. modif: 01

43-10-409-62

ICSITFE
Bucuresti

Scara:

1:1

Data: 2071976

Garnitură 540x5

Stator exterior

EPA 500-18

AL 1217-2071

1 buc / pompa

Art. ref:

A 4192 - 90

Rev:

b


Fig:

7

A - A

Scara: 2:1

S max 0,45



A



A

$\phi 605 \pm 1,6$

$\phi 8 \pm 0,2$

18 buc / pompa

Proiectat	Scrima V	PTH 70	177	43-12-411-00
Verificat	Ing Calman M	STAS 7278-82		
Construit	Ing Calman M	Masa neta 0,166 Kg	Mr. modif	
Montat	Ing Olaru Gh	Scara 1,5		
		(2:1)		
ICSITEE Bucuresti		Data: aug 1976	Stator interior	LEPA 500-180

Copiat Rusu R
Verificat Gutuescu
Aprobat Ing Breian D

Original deteriorat
43-12-411-00/a

Nr. ref:


A 4194-03

Rev:

a

Poz:

13

 $\phi 720$

05

1 buc / pompa

Proiectat

Desenat

Verificat

Contr. Stas

Aprobat

Stefan E

Ing. Calman

Ing. Calman

Ing. Olaru G

PTH 70

STAS 7278-82

Masa netă 001,4 kg

Scara

1:1

Data 5.07.1976

77b

43-10-409-63

Nr. modif: 0

ICSITEE
Bucuresti

Garnitură 720x5

Stator exterior

EP4500-

An 1210-297

Data 3.8.9

Ducel 4 V 1

Copie DRAGANESCU J. J.

Verificat Ing. PRIFTI ST

Aprobat Ing. BRETAN D

ICSITEE - Col. Pompa

Original deteriorat

43-10-409-63/a